

Date: Wednesday, 06/09/2006 11:04:20 AM  
 User: Linda Lacelle

## Process Sheet

<b>Customer</b> : CU-DAR001 Dart Helicopters Services	<b>Drawing Name</b> : GPS RECEIVER HOUSING
<b>Job Number</b> : 28416	
<b>Estimate Number</b> : 12516	
<b>P.O. Number</b> : N/A	<b>Part Number</b> : D3514041
<b>This Issue</b> : 06/09/2006 <b>S.O. No.</b> : N/A	<b>Drawing Number</b> : UNDER REVIEW <i>06.09.05</i>
<b>Prsht Rev.</b> : NC	<b>Project Number</b> : N/A
<b>First Issue</b> : N/A <b>Type</b> : SMALL /MED FAB	<b>Drawing Revision</b> : N/A
<b>Previous Run</b> : N/A	<b>Material</b> : N/A
<b>Written By</b> : <i>CE</i>	<b>Due Date</b> : 13/09/2006 <b>Qty:</b> 1 <b>Um:</b> Each
<b>Checked &amp; Approved By</b> :	
<b>Comment</b> : Est Rev:A New Issue 06-08-30 EC	

Additional Product

PRELIMINARY ISSUE

Job Number:



<b>Seq. #:</b>	<b>Machine Or Operation:</b>	<b>Description :</b>
----------------	------------------------------	----------------------

1.0	D35141	BOX TOP (BOTTOM MOUNTED)
-----	--------	--------------------------



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

BOX TOP (BOTTOM MOUNTED)

Batch: *B28359**CB 07.03.08*

2.0	D35145	BOX BOTTOM (BOTTOM MOUNTED)
-----	--------	-----------------------------



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

BOX BOTTOM (BOTTOM MOUNTED)

Batch: *B28357**CB 07.03.08*

3.0	D35149	HOOD
-----	--------	------



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

HOOD

Batch: *B28358**CB 07.03.08*

4.0	D3524041	UPPER AND LOWER PLATE
-----	----------	-----------------------



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

UPPER AND LOWER PLATE

Batch: *00053A**CB 07.03.08*

5.0	MS21072L06	ANCHOR NUT
-----	------------	------------



**Comment:** Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

ANCHOR NUT

Batch: *M10760**SB 07/03/08*

**Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Wednesday, 06/09/2006 11:04:20 AM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GPS RECEIVER HOUSING

Job Number: 28416

Part Number: D3514041

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

MS20426AD34

RIVET



Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s)

RIVET

Batch: M19099

SB 07/03/08

7.0

MS20426AD45

Rivet



Comment: Qty.: 11.0000 Each(s)/Unit Total: 11.0000 Each(s)

Rivet

Batch: M4067

SB 07/03/08

8.0

MS20426AD48

RIVET



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

RIVET

Batch: M18136

SB 07/03/08

9.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg D3514

SB 07/03/08

10.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

FE 07.03.08

11.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat Black Sandtex (Ref: 4.3.5.7) as per QSI 005 4.3

not needed  
For testing  
CB

12.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

not needed  
For testing  
CB

13.0

D35211

MISSING

BALL



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

BALL

Batch: 624532

28359

CB 07.03.08

**Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Wednesday, 06/09/2006 11:04:20 AM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GPS RECEIVER HOUSING

Job Number: 28416

Part Number: D3514041

Job Number:



Seq. #:

Machine Or Operation:

Description :

14.0

D35221



GASKET



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

GASKET

Batch: 16283607

15.0

D35231



LEG



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

LEG

Batch: 60053A

16.0

D35241



LOWER PLATE



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

LOWER PLATE

Batch: 60053A

17.0

D35261



RUBBER SEAL



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

RUBBER SEAL

Batch:

not needed  
for testing  
CB

18.0

AN316A



Bolt



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Bolt

Batch: 101884

CB 07.03.08

19.0

AN936B10



WASHER



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WASHER

Batch: 101760

CB 07.03.08

20.0

AN960JD10



Washer



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Washer

Batch: 100274

CB 07.03.08

**Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes ☐ No ☒ DQA: ☒ Date: 07/27/24  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Wednesday, 06/09/2006 11:04:20 AM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GPS RECEIVER HOUSING

Job Number: 28416

Part Number: D3514041

Job Number:



Seq. #:

Machine Or Operation:

Description :

21.0

MS24693S27 29 CB 07.03.08

SCREW



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

SCREW

Batch: M102147

CB 07.03.08

22.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg D3514

23.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

24.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: \_\_\_\_\_

N/A  
prototype  
CB

25.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: Inspection Level 21

(1)

07/07/04

Job Completion



Part went to HAI. Part not approved and not airworthy.  
CB 07.07.13

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



# PRELIMINARY ISSUE


Package  
# 3

DESIGN CB	DRAWN BY CB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DRAWING NO. D3514	REV. A SHEET 1 OF 7
DATE 06.05.03	TITLE GPS RECEIVER HOUSING SCALE 1:4		
A	06.05.03	NEW ISSUE	


UNDER REVIEW

06.08.22 CB

prototype




MS21072-06 ANCHOR NUT (1)  
MS20426AD3-4 RIVETS (2)  
(4 PLACES)



SECTION A-A

AN3-16A BOLT  
AN960JD10 WASHER  
AN936-B10 WASHER  
TIGHTEN TO SNUG FIT ONLY



MS20426AD4-5  
RIVETS (8 PLACES)

MS20426AD4-5  
RIVETS (3 PLACES)

D3526-1

D3514-9

MS20426AD4-8  
RIVETS (4 PLACES)

PARTS LIST

QTY.	P/N	DESCRIPTION
X	D3514-041	BOTTOM MOUNTED GPS RECEIVER HOUSING
1 ✓	D3514-1	BOX TOP (BOTTOM MOUNTED) ✓
1 ✓	D3514-5	BOX BOTTOM (BOTTOM MOUNTED) ✓
1 ✓	D3514-9	HOOD ✓
1	D3521-1	BALL - missing
1	D3522-1	GASKET - missing
1	D3523-1	LEG ✓ X
1	D3524-1	LOWER PLATE X workorder, not called up
1 ✓	D3524-041	UPPER PLATE ASSEMBLY ✓ X no workorder, called up
1	D3526-1	RUBBER SEAL missing
1	AN3-16A	BOLT missing
1	AN936-B10	WASHER missing
1	AN960JD10	WASHER missing
8 ✓	MS20426AD3-4	RIVET M19099
11 ✓	MS20426AD4-5	RIVET M4067
4 ✓	MS20426AD4-8	RIVET M18136
4 ✓	MS21072L06	ANCHOR NUT M10760
4	MS24693-S27	SCREWS missing

MS24693-S27  
SCREWS (4 PLACES)

## D3514-041 GPS RECEIVER HOUSING (BOTTOM MOUNTED)

### NOTE:

1) POWDER COAT ASSEMBLY OF D3514-1, D3514-5, D3514-9, D3524-041 AND MS21072-06 BLACK SANDTEX (4.3.5.7) PER DART QSI 005 4.3.

2) INSTALL D3521-1, D3522-1, D3523-1, D3524-1 AND D3526-1 AFTER PAINT

COPYRIGHT © 2006 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.